Shamir Autograph Plus™

Product Availability and Markings

Material	Index	Power Range	Nominal Base Curve*	Add	Color	Fitting Height (X)	Invisible Marking	
Hard Resin	1.498	-12.25 to +6.00	0.5, 2, 3.75, 4.25, 5.25, 6, 7, 8	0.75 to 3.50	Clear	14, 16, 18	15 ⑤ +X	S 250
Transitions®	1.5	-12.25 to +6.00	0.5, 2, 3.75, 4.25, 5.25, 6, 7, 8	0.75 to 3.50	Gray & Brown	14, 16, 18	TR S +X	S 250
Transitions® XTRActive™	1.5	-12.25 to +6.00	0.5, 2, 3.75, 4.25, 5.25, 6, 7, 8	0.75 to 3.50	Gray	14, 16, 18	X5 \$\ +X	S 250
Polarized	1.498	-12.25 to +6.00	0.5, 2, 3.75, 4.25, 5.25, 6, 7, 8	0.75 to 3.50	Gray & Brown	14, 16, 18	PZ S +X	S 250
Drivewear [®]	1.5	-12.25 to +6.00	0.5, 2, 3.75, 4.25, 5.25, 6, 7, 8	0.75 to 3.50	Drivewear®	14, 16, 18	DW S +X	© 250
DLC™ (Trivex)	1.53	-13.25 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Clear	14, 16, 18	TX S +X	S 250
DLC™ (Trivex) Transitions®	1.53	-13.25 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Gray & Brown	14, 16, 18	TTX S +X	© 250
DLC™ (Trivex) Polarized	1.53	-13.25 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Gray & Brown	14, 16, 18	PTX S +X	© 250
1.56	1.56	-14.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Clear	14, 16, 18	56 \$ +X	© 250
Polycarbonate	1.586	-14.75 to +6.50	0.5, 2, 3, 4, 5.25, 6.25, 7.5	0.75 to 3.50	Clear	14, 16, 18	PC S +X	S 250
Polycarbonate Transitions®	1.586	-14.75 to +6.50	0.5, 2, 3, 4, 5.25, 6.25, 7.5	0.75 to 3.50	Gray & Brown	14, 16, 18	PT S +X	© 250

^{*} The true base curve can be selected from a range of curves that has been defined in the Freeform Software.



Shamir Autograph Plus™

Product Availability and Markings

Material	Index	Power Range	Nominal Base Curve*	Add	Color	Fitting Height (X)	Invisible Marking	
Polycarbonate Transitions® XTRActive™	1.586	-14.75 to +6.50	0.5, 2, 3, 4, 5.25, 6.25, 7.5	0.75 to 3.50	Gray	14, 16, 18	PX S +X	© 250
Polycarbonate Polarized	1.586	-14.75 to +6.50	0.5, 2, 3, 4, 5.25, 6.25, 7.5	0.75 to 3.50	Gray & Brown	14, 16, 18	PPZ S +X	© 250
Polycarbonate Drivewear®	1.586	-14.75 to +6.50	0.5, 2, 3, 4, 5.25, 6.25, 7.5	0.75 to 3.50	Drivewear®	14, 16, 18	PD S +X	© 250
Superlite™ 1.6	1.6	-15.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Clear	14, 16, 18	16 \$ +X	© 250
Superlite 1.6 Transitions®	1.6	-15.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Gray & Brown	14, 16, 18	T6 \$ +X	© 250
Superlite 1.6 Transitions® XTRActive™	1.6	-15.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Gray	14, 16, 18	X6 \$ +X	© 250
Superlite 1.6 Polarized	1.6	-15.00 to +6.00	0.5, 2, 3, 4, 5, 6, 7	0.75 to 3.50	Gray & Brown	14, 16, 18	PZ6 S +X	© 250
Superlite 1.67	1.67	-16.75 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Clear	14, 16, 18	67 \$\ +X	© 250
Superlite 1.67 Transitions®	1.67	-16.75 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Gray & Brown	14, 16, 18	T67 ⑤ +X	S 250
Superlite 1.67 Transitions® XTRActive™	1.67	-16.75 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Gray	14, 16, 18	X67 \$ +X	© 250
Superlite 1.67 Polarized	1.67	-16.75 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Gray & Brown	14, 16, 18	PZ67 ⑤ +X	© 250
Superlite 1.74	1.74	-18.75 to +14.75	0.5, 1.5, 2.5, 3.5, 4.75, 6, 7.25, 8.25, 9, 9.75, 10.5, 11.25, 12	0.75 to 3.50	Clear	14, 16, 18	74 \$\bigs\tau+X	S 250

st The true base curve can be selected from a range of curves that has been defined in the Freeform Software.



Shamir Autograph Plus™ Mineral

Product Availability and Markings

Material	Index	Power Range	Nominal Base Curve*	Add	Color	Fitting Height (X)	Invisible Marking	
1.60 White	1.6	-10.00 to +6.00	2, 3, 4, 5, 6, 7	0.75 to 3.50	Clear	14, 16, 18	G16 S +X	© 250
1.60 Photochromic Gray	1.6	-10.00 to +6.00	2, 3, 4, 5, 6, 7	0.75 to 3.50	Gray	14, 16, 18	GP16 S +X	© 250
1.60 Photochromic Brown	1.6	-10.00 to +6.00	2, 3, 4, 5, 6, 7	0.75 to 3.50	Brown	14, 16, 18	GP16 S +X	© 250

^{*} The true base curve can be selected from a range of curves that has been defined in the Freeform Software.

