

Product Availability and Markings

Shamir Computer™

Material	Index	Power Range (Near)	Nominal Base Curve*	Continuous Dynamic Power[D]	Color	Fitting Height	Invisible Marking
Hard Resin	1.498	-6.00 to +6.00	2, 3.75, 5.25, 6.50, 8	-0.75 to -2.00	Clear	14mm	15 FFC 14
Transitions®	1.5	-6.00 to +6.00	2, 3.75, 5.25, 6.50, 8	-0.75 to -2.00	Gray & Brown	14mm	TR FFC 14
Transitions® XTRActive™	1.5	-6.00 to +6.00	2, 3.75, 5.25, 6.50, 8	-0.75 to -2.00	Gray	14mm	X5 FFC 14
DLC™ (Trivex)	1.53	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.00	Clear	14mm	TX FFC 14
DLC™ (Trivex) Transitions®	1.53	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.00	Gray & Brown	14mm	TTX FFC 14
DLC™ (Trivex) Transitions® XTRActive™	1.53	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.00	Gray	14mm	XX FFC 14
1.56	1.56	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.00	Clear	14mm	56 FFC 14
Superlite™ 1.6	1.6	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.00	Clear	14mm	16 FFC 14
Superlite 1.6 Transitions®	1.6	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.00	Gray & Brown	14mm	T6 FFC 14
Superlite 1.6 Transitions® XTRActive™	1.6	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.00	Gray	14mm	X6 FFC 14

* The true base curve can be selected from a range of curves that has been defined in the Freeform Software.



Product Availability and Markings

Shamir WorkSpace™

Material	Index	Power Range (Near)	Nominal Base Curve*	Continuous Dynamic Power[D]	Color	Fitting Height	Invisible Marking
Hard Resin	1.498	-6.00 to +6.00	2, 3.75, 5.25, 6.50, 8	-0.75 to -2.50	Clear	14mm	15 ☉ FFW 14
Transitions®	1.5	-6.00 to +6.00	2, 3.75, 5.25, 6.50, 8	-0.75 to -2.50	Gray & Brown	14mm	TR ☉ FFW 14
Transitions® XTRActive™	1.5	-6.00 to +6.00	2, 3.75, 5.25, 6.50, 8	-0.75 to -2.50	Gray	14mm	X5 ☉ FFW 14
DLC™ (Trivex)	1.53	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.50	Clear	14mm	TX ☉ FFW 14
DLC™ (Trivex) Transitions®	1.53	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.50	Gray & Brown	14mm	TTX ☉ FFW 14
DLC™ (Trivex) Transitions® XTRActive™	1.53	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.50	Gray	14mm	XX ☉ FFW 14
1.56	1.56	-6.00 to +8.00	2, 3, 5, 6, 8	-0.75 to -2.50	Clear	14mm	56 ☉ FFW 14
Superlite™ 1.6	1.6	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.00	Clear	14mm	16 ☉ FFC 14
Superlite 1.6 Transitions®	1.6	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.00	Gray & Brown	14mm	T6 ☉ FFC 14
Superlite 1.6 Transitions® XTRActive™	1.6	-6.00 to +8.00	2, 3, 5, 6.25, 8, 9.5	-0.75 to -2.00	Gray	14mm	X6 ☉ FFC 14

* The true base curve can be selected from a range of curves that has been defined in the Freeform Software.