

Regular

Product Availability and Markings

Material	Index	Power Range	Nominal Base Curve	Size	Add	Color	Fitting Height	Invisible Marking	
Hard Resin	1.498	-8.25 to +5.75	1.5, 3, 5, 6.5, 7.5	75/80	0.75 to 3.50	Clear	19mm	X	X 250
Superlite™ 1.6	1.6	-11.25 to +7.00	1.5, 3, 5, 6.5, 7.5	75/80	0.75 to 3.50	Clear	19mm	X H	X 250
Superlite 1.6 Transitions®	1.6	-11.25 to +7.00	1.5, 3, 5, 6.5, 7.5	72/77	0.75 to 3.50	Gray & Brown	19mm	X H	X 250
Superlite 1.67	1.67	-12.50 to +7.50	1.5, 3, 5, 6.5, 7.5	75/80	0.75 to 3.50	Clear	19mm	✧ H67	✧ 250
Superlite 1.67 Transitions®	1.67	-12.50 to +7.50	1.5, 3, 5, 6.5, 7.5	72/77	0.75 to 3.50	Gray & Brown	19mm	✧ H67	✧ 250
Glass	1.523	-5.25 to +6.00	3,5,7	71/76	0.75 to 3.50	Clear, PSSB and PSSG	18mm	X	X 250
Glass	1.6	-9.00 to +6.00	1.5, 3, 5, 7	70/75	0.75 to 3.50	Clear, PGX, PBX	19mm	X H	X 250
Glass	1.7	-12.00 to -6.00	2	70/75	0.75 to 3.50	Clear	19mm	X H7	X 250
Glass	1.8	-20.0 to -4.25	1.5, 2	65/69	1.00 to 3.00	Clear	19mm	◇ 18	◇ 25